



EASA CS ADR-DSN.E.360

Sklony na odbavovací ploše JIH

Sklony musí být dostatečné k zabránění shromažďování vody na povrchu, avšak co nejmenší, jak požadavky na odvodnění dovolí. Na stání nesmí max. sklon přesáhnout 1 %.

Odbavovací plocha JIH má známou zvláštnost. Podélné sklony jsou značně větší, než požaduje předpis. Dosahují hodnot 1,4 %, 1,8 % a 2,4 % a nelze je snížit z důvodu návaznosti na okolní TWYs a hangáry. Negativní vliv na bezpečnost dosud nebyl zaznamenán.

Upozornujeme na nutnost důsledného zabezpečení letadel a mobilních prostředků proti samovolnému pohybu.

EASA ADR-DSN.E.360 Slopes on APN SOUTH

Slopes should be sufficient to prevent accumulation of water on the surface of the apron but should be kept to the minimum required to facilitate effective drainage. On an aircraft stand the maximum slope should not exceed 1 % in any direction.

Apron SOUTH has an unusual attribute.

Longitudinal slopes are considerably larger than permitted, reaches 1.4%, 1.8% and 2.4%.

Reduction is not possible because of the surrounding TWYs and historical hangars. Negative impact on safety has not been recorded.

Keep in mind the need of protection of aircraft and GSE against accidental movement.

