

Safety briefs 54

Poruchy dveří u COBUS C3000

Vážení kolegové,

na námi provozovaných autobusech COBUS C3000, r.v. 2017, opakovaně došlo k poruše pneumatického otevírání dveří, při níž se bez zásahu obsluhy uvolnily a otevřely pravé dveře kabiny cestujících. Uvolnění dveří následovalo po prasknutí modré hadičky pneumatického systému otevírání dveří, pravděpodobně v souvislosti se zapnutým topením a poškozením hadičky teplem.

Pokud se u vás vyskytl výše popsáný problém, ozvěte se nám, prosím, na adresu safety@prg.aero.



Failure of doors of COBUS C3000

Dear safety partners,

operation of COBUS C3000, year of production 2017, operated at PRG was repeatedly affected by a pneumatic door opening failure. Release and opening the right door of the passenger cabin has occurred spontaneously without the control of the operator and followed after the break-out of the blue hose of pneumatic door-opening system, which probably was caused by a heat damage when cab heating was turned on.

If you have the problem described above, please share with us at safety@prg.aero.

