



Safety Brief 138

Intended for/dedicated to: *All*
Issued: *January 2026*

Two aircraft damaged during de-icing

During de-icing, a deicer collided with the wing of an aircraft.
While taxiing from the de-icing stand, the aircraft winglet collided with a parked deicer.



The causes are under investigation.
Be cautious during de-icing and always check for a safe distance.